

No.: SHIN2002006126MR

Date: Mar 11, 2020

Page: 1 of 7

CUSTOMER NAME: CIXI LEONLUX TECHNOLOGY CO.,LTD

ADDRESS: NO.36 XUJIA, YIYUAN VILLAGE, ZONGHAN STREET, CIXI 315300,

**CHINA** 

Sample Name : LED luminaire

Product Specification: 33A02, 33A03, 33A04

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

\*\*\*\*\*\*

SGS Ref. No. : NBES2002000463TX

Date of Receipt : Feb 26, 2020
Testing Start Date : Feb 26, 2020
Testing End Date : Mar 11, 2020

Test result(s) : For further details, please refer to the following page(s)

(Unless otherwise stated the results shown in this test report refer only to

the sample(s) tested)

Signed for

SGS-CSTC Standards Technical Service (Shanghai)Co., Ltd.

Jane Deng

Authorized signatory





No.: SHIN2002006126MR

Date: Mar 11, 2020

Page: 2 of 7

### Summary of Results:

No.	Test Item	Test Method	Result	Conclusion
1 IP6X	IEC 60529:1989/AMD2:2013/COR1:2019	No dust ingress	1	
	and client's requirement	140 dust ingress	,	
2	IPX9K	ISO 20653:2013 and client's requirement	No water ingress	/

Note: Pass: Meet the requirements;

Fail: Does not meet the requirements;

/: Not Apply to the judgment.

#### Original Sample:







No.: SHIN2002006126MR

Date: Mar 11, 2020

Page: 3 of 7

Test Item: IP6X

Sample Description: LED luminaire

Test Method: IEC 60529:1989/AMD2:2013/COR1:2019

Client's requirement: No negative pressure

Test Condition:

Test Dust: Talcum powder

Dust Concentration: 2 kg/m³ chamber volume and be kept in suspension during the test

Test Duration: 8 hours

Lab Environment Condition: 18 °C ~28 °C, 25%RH~75%RH

Test Result:

Sample No	Test result
1	No dust ingress.

#### Test Photo:



**During Test** 






No.: SHIN2002006126MR

Date: Mar 11, 2020

Page: 4 of 7



#### **Equipment Information:**

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Dust test chamber	TK6070iQ	P-614	2019-10-18	2020-10-17



No.69, Block 1159, East Kang Qiao Road, Pudong District, Shanghai, China 201319 中国・上海・浦东康桥东路1159弄69号 邮编: 201319

 $\begin{array}{llll} t(86-21)\,61196300 & f(86-21)\,68183122/68183920 & www.sgsgroup.com.cn \\ t(86-21)\,61196300 & f(86-21)\,68183122/68183920 & e sgs.china@sgs.com \end{array}$ 



No.: SHIN2002006126MR

Date: Mar 11, 2020

Page: 5 of 7

2. Test Item: IPX9K

Test Method: ISO 20653:2013

Client's requirement: Turntable not rotating

**Test Condition** 

Jet angle: 2507

Water flow: (14~16) L/min

Water pressure: (8000~10000) kPa

Water temperature: (80±5) °C Test angle: 0°, 30°, 60°, 90°


Test distance from jet to Sample: (100~150) mm

Test duration: 30 s/position

#### Test Result:

Sample No	Test result
1	No water ingress.

#### Test photo:





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions\_agry and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of fits document sadvised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction document. This document cannot be reproduced except in full, without prior written approval of the Company, Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) lested and such sample(s) are retained for 30 days only.


No.69, Block 1159, East Kang Qiao Road, Pudong District, Shanghai, China 201319 中国・上海・浦东康桥东路1159弄69号 邮编: 201319



No.: SHIN2002006126MR

Date: Mar 11, 2020

Page: 6 of 7





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="http://www.sgs.com/en/Terms-and-Conditions.aspx">http://www.sgs.com/en/Terms-and-Conditions.aspx</a> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx">https://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document sadvised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this occument ose not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443,



No.: SHIN2002006126MR

Date: Mar 11, 2020

Page: 7 of 7



### **Equipment Information:**

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
High pressure water device	HDS 13/20-4 S	P-279	2019-12-20	2020-12-19
Pressure gauge	0-6000Psi	P-279-1	2019-4-22	2020-4-21
Steel ruler	0-30 cm	P-279-3	2019-12-10	2020-12-9

\*\*\*\*\*\* End of report\*\*\*\*\*\*

